



VEHICLE INSPECTION REPORT

GU60EEX

Ford Fiesta 1.4 Zetec 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	01/09/2010	Body Style	Hatchback	Last service miles	70,154
Year	2010	Keys	1	MOT Due	Expired
Mileage	75,117 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	5
Colour	BLUE	Number of stamps	14	Doors	5
VIN	WF0JXXWPJJAY10411	Last service date	22/08/2024		

LAST SERVICE 22/08/2024 @ 70,154 MILES (14 SERVICES) Ignition barrel sticky


Tyres

NSF	HANKOOK	5.0mm
NSR	APLUS	4.0mm
OSF	KUMHO	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- PAS
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Passenger airbag
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Central locking
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Remote central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wheel nsf
Scratched
Up To 50mm




4: Wing nsf
Chipped
1 To 5



5: Door nsf
Dented
2 Or Less UpTo 10mm



6: Door nsf
Chipped
Over 5mm



7: Door nsr
Chipped
1 To 5



8: Door nsr
Dented
2 Or Less UpTo 10mm



9: Qtr Panel nsr
Poor Previous Repair
Poor Paint



10: Bumper Rear
Poor Previous Repair
Poor Paint



11: Tailgate
Poor Previous Repair
Poor Colour



12: Qtr Panel osr
Dented
Between 10mm + 30mm




13: Qtr Panel osr
Chipped
1 To 5



14: Wheel osr
Scratched
Over 50mm



15: Door osr
Chipped
Edge Chip



16: Door osf
Scratched
Over 25mm Thru Paint



17: Wing osf
Chipped
1 To 5



18: Wheel osf
Scratched
Over 50mm



19: Screen Front
Cracked
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK