



VEHICLE INSPECTION REPORT

HN70DJX

MG Mg Hs EXCITE DCT

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
2

Details

Reg. date	26/01/2021	VIN	LSJA24U91LN047963	Number of stamps	2
Year	2021	Body Style	Estate	Last service date	30/10/2024
Mileage	31,765 Miles Warranted	Keys	2	Last service miles	19,113
Fuel Type	Petrol	Service history	Yes	Gearbox	SEMI AUTO
Colour	BLACK	Service documents	Printout	Gears	7

£90 ADDITIONAL FEE

MOT EXPIRED - needs transporting offsite

LAST SERVICE 30/10/2024 @ 19,113 MILES (2 SERVICES, 1 MAIN DEALER) Eml light on car has been plugged in and detects transmission control system (MIL REQUEST)

Hydraulic pump relay circuit open

Tyres

NSF	MICHELIN	Damaged
NSR	MICHELIN	5.0mm
OSF	MICHELIN	3.0mm
OSR	MICHELIN	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Cruise control
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Park assist camera
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Up To 50mm



2: Door osf
Chipped
1 To 5



3: Door osf
Chipped
Edge Chip



4: Door osr
Chipped
1 To 5



5: Door osr
Dented
Between 10mm + 30mm



6: Wheel osr
Corroded
Light



7: Qtr Panel osr
Chipped
1 To 5



8: Bumper Rear
Scratched
Over 100mm Thru Paint




9: Door nsf
Chipped
1 To 5



10: Wheel nsf
Corroded
Light



11: Bumper Front
Chipped
1 To 5



12: Bonnet
Chipped
1 To 5



13: Tyre nsf
Damaged
Replace



14: Qtr Panel nsr
Dented
Between 10mm + 30mm



15: Door nsr
Chipped
1 To 5

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK