



VEHICLE INSPECTION REPORT

HK65UMX

Kia Sorento 2.2 CRDi KX-2 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	22/02/2016	Body Style	Estate	Last service miles	161,250
Year	2016	Keys	2	MOT Due	06/01/2027
Mileage	161,545 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	DIESEL	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	11	Doors	5
VIN	KNAPH81BNG5147258	Last service date	06/08/2026		

£100 ADDITIONAL FEE
LAST SERVICE 06/08/2026 @ 161,250 MILES (11 SERVICES)

Tyres

NSF	FALKEN	3.0mm
NSR	FALKEN	5.0mm
OSF	FALKEN	3.0mm
OSR	FALKEN	3.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Seat Base Cover osf
Torn
UpTo 3mm



2: Wheel osf
Corroded
Light



3: Wing osf
Chipped
1 To 5



4: Wheel osr
Corroded
Light



5: Roof
Dented
With Paint Damage



6: Wheel nsr
Corroded
Light



7: Wheel nsf
Corroded
Light



8: Wing nsf
Chipped
1 To 5



9: Door osf
Chipped
1 To 5



10: Door osr
Chipped
1 To 5



11: Qtr Panel osr
Chipped
1 To 5



12: Bumper Rear
Dented
Between 10mm + 30mm



13: C Post ns
Poor Previous Repair
Paint Flake



14: Door nsr
Chipped
1 To 5



15: Door nsf
Dented
2 Or Less UpTo 10mm

16: Bumper Front
Chipped
Multiple Chips



17: Bonnet
Chipped
1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK