



VEHICLE INSPECTION REPORT

PN12VYK

Nissan Juke 1.6 Acenta 5dr [Premium Pack]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	06/03/2012	Body Style	Hatchback	CAP Below	£825.00
Year	2012	Keys	1	Gearbox	MANUAL
Mileage	85,742 Miles Warranted	Service history	None	Gears	5
Fuel Type	PETROL	MOT Due	13/08/2027	Doors	5
Colour	RED	CAP Clean	£1,625.00		
VIN	SJNFBAF15U6124544	CAP Average	£1,225.00		

£100 ADDITIONAL FEE
NO SERVICE HISTORY Radio is locked

Tyres

NSF	BUDGET	5.0mm
NSR	RAPID	4.0mm
OSF	BUDGET	4.0mm
OSR	RAPID	5.0mm
Spare		

Features


- Bluetooth connection
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Cruise control
- Radio/CD
- Climate control
- Metallic Paint
- Traction control
- Alloy wheels
- Navigation system
- Body coloured bumpers
- Front electric windows
- ABS
- Central locking
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Remote central locking

Photos






Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Dented
2 Or Less UpTo 10mm



3: Wing osf
Chipped
1 To 5




4: Door osf
Poor Previous Repair
Poor Paint



5: Door osr
Dented
With Paint Damage



6: Wheel osr
Scratched
Over 50mm




7: Qtr Panel osr
Poor Previous Repair
Poor Paint



8: Bumper Rear
Poor Previous Repair
Paint Flake




9: Tailgate
Poor Previous Repair
Poor Paint



10: Qtr Panel nsr
Poor Previous Repair
Poor Paint



11: Wheel nsr
Scratched
Over 50mm



12: Door nsr
Scratched
Over 25mm Thru Paint



13: Door nsf
Dented
With Paint Damage



14: Wheel nsf
Scratched
Over 50mm



15: Bumper Front
 Scratched
 Over 100mm Thru Paint



16: Bonnet
 Chipped
 1 To 5



17: Screen Front
 Chipped
 UpTo 10mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	Fault
		Steering	OK