



VEHICLE INSPECTION REPORT

MW63CYV

Ford Focus 1.6 125 Zetec Navigator 5dr Powershift

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	08/01/2014	VIN	WF0KXXGCBKDD17026	Gearbox	AUTOMATIC
Year	2014	Body Style	Hatchback	Gears	6
Mileage	80,208 Miles Warranted	Keys	1	Doors	5
Fuel Type	PETROL	Service history	None		
Colour	BLACK	MOT Due	23/11/2026		

no service history

Tyres

NSF	TRIANGLE	4.0mm
NSR	BUDGET	5.0mm
OSF	TRIANGLE	4.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Radio/CD
- Front armrest
- ABS
- Central locking
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- Drivers airbag
- Remote central locking
- Rear wiper
- Electric door mirrors
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Telephone
- Air conditioning
- Solid Paint
- Traction control
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Wing osf
Poor Previous Repair
Poor Paint



2: Door osf
Poor Previous Repair
Poor Paint



3: Door osf
Scratched
UpTo 25mm Thru Paint



4: Door osr
Chipped
Edge Chip



5: Qtr Panel osr
Chipped
1 To 5



6: Bumper Rear
Scratched
Up To 25mm Thru Paint



7: Qtr Panel nsr
Dented
Between 10mm + 30mm



8: Door nsr
Dented
Over 30mm



9: Door nsf
Dented
2 Or Less UpTo 10mm



10: Door nsf
Chipped
1 To 5



11: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



12: Wheel nsf
Scratched
Over 50mm



13: Bumper Front
Chipped
Multiple Chips



14: Bonnet
Poor Previous Repair
Paint Flake



15: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK