



VEHICLE INSPECTION REPORT

GX70YVY

Nissan X-Trail 1.7 dCi Tekna 5dr CVT

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	12/09/2020	Body Style	Estate	MOT Due	Expired
Year	2020	Service history	Yes	Gearbox	CVT
Mileage	47,725 Miles Warranted	Service documents	Service Book	Gears	6
Fuel Type	DIESEL	Number of stamps	6	Doors	5
Colour	GREY	Last service date	05/09/2025		
VIN	JN1THAT32U0005168	Last service miles	41,239		

£90 ADDITIONAL FEE

Last Service - 05.09.2025 at 41239 miles (6 main dealer services)

MOT EXPIRED Ad blue message displayed

Tyres

NSF	MAXTREK	5.0mm
NSR	MAXTREK	5.0mm
OSF	MAXTREK	5.0mm
OSR	MAXTREK	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Body coloured bumpers
- Roof rails
- Electrically adjustable passenger seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Cruise control
- Park assist camera
- Service indicator
- Electric door mirrors
- Space saver spare wheel
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Front parking sensor
- PAS
- Steering wheel mounted controls
- Front fog lights
- Air conditioning
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Heated front seat
- Rear parking sensor
- Digital radio
- Opening panoramic glass roof
- Electrically adjustable drivers seat
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wing nsf
Scratched
UpTo 25mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Door nsr
Scratched
UpTo 25mm Thru Paint



7: Wheel nsr
Scratched
Over 50mm



8: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



9: Tailgate
Scratched
Over 25mm Thru Paint



10: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



11: Wheel osr
Scratched
Over 50mm



12: Door osr
Chipped
1 To 5



13: Door osf
Dented
2 Or Less UpTo 10mm



14: Door osf
Chipped
Edge Chip



15: Wing osf
Chipped
1 To 5



16: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition -
Seat Condition -

Upholstery Condition -
Odour -

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		