



VEHICLE INSPECTION REPORT

SY69HKM

Honda Civic 1.0 VTEC Turbo 126 SR 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	11/10/2019	Body Style	Hatchback	Last service miles	27,857
Year	2019	Keys	1	MOT Due	13/05/2027
Mileage	35,215 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	4	Doors	5
VIN	SHHFK6760KU002406	Last service date	20/09/2024		

£100 ADDITIONAL FEE

Last Service - 20.09.2024 at 27857 miles (4 services) Traction light on
Collision light on
Lane assist fault on dash

Tyres

NSF	ROTALLA	5.0mm
NSR	PIRELLI	5.0mm
OSF	ROTALLA	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Park assist camera
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Door osf
Chipped
Edge Chip



3: Door osr
Chipped
1 To 5



4: Wheel osr
Scratched
Over 50mm



5: Qtr Panel osr
Scratched
Over 25mm Thru Paint



6: Bumper Rear
Scratched
Over 100mm Thru Paint



7: Wheel nsr
Scratched
Over 50mm



8: Door nsr
Chipped
1 To 5



9: Door nsf
Dented
Between 10mm + 30mm



10: Wheel nsf
Scratched
Over 50mm



11: Wing nsf
Dented
2 Or Less UpTo 10mm



12: Bumper Front
Scratched
25 to 100mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK