



VEHICLE INSPECTION REPORT

OV12JJU

Honda Jazz 1.4 i-VTEC EX 5dr CVT

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	16/04/2012	Service history	Yes	CAP Average	£4,550.00
Year	2012	Service documents	Service Book	CAP Below	£3,825.00
Mileage	44,096 Miles Warranted	Number of stamps	13	Gearbox	CVT
Fuel Type	Petrol	Last service date	04/12/2024	Gears	1
Colour	BROWN	Last service miles	43,045	Doors	5
VIN	SHHGG6880CU022106	MOT Due	09/06/2026		
Body Style	Hatchback	CAP Clean	£5,225.00		

Last Service - 04.12.2024 at 43045 miles (13 services)

Tyres

NSF	MAXXIS	4.0mm
NSR	BRIDGESTONE	4.0mm
OSF	HANKOOK	4.0mm
OSR	BRIDGESTONE	4.0mm
Spare		

Features


- PAS
- Radio/CD
- Climate control
- Rear electric windows
- ABS
- Central locking
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Rear headrests
- Drivers airbag
- Remote central locking
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Cloth seat trim
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bumper Rear
Scratched
Over 100mm Thru Paint



2: Qtr Panel nsr
Dented
Over 2 UpTo 10mm



3: Wheel nsr
Scratched
Over 50mm



4: Door nsr
Dented
With Paint Damage



5: Door nsf
Poor Previous Repair
Paint Flake



6: Wing nsf
Scratched
Over 25mm Thru Paint



7: Wheel nsf
Scratched
Over 50mm



8: Bonnet
Chipped
1 To 5



9: Bumper Front
Scratched
Over 100mm Thru Paint



10: Wheel osf
Scratched
Over 50mm



11: Wing osf
Chipped
1 To 5



12: Door osf
Chipped
Multiple Chips



13: Door osr
Dented
Between 10mm + 30mm



14: Door osr
Chipped
1 To 5



15: Wheel osr
Scratched
Over 50mm



16: Qtr Panel osr
Chipped
1 To 5

Interior

Carpet Condition -
Seat Condition -

Upholstery Condition -
Odour -

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK