



VEHICLE INSPECTION REPORT

GP23CVZ

Mini Hatchback 1.5 Cooper Exclusive Premium Plus 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	21/07/2023	Colour	GREEN	MOT Due	20/07/2027
Year	2023	VIN	WMW32DK0302V07567	Gearbox	AUTOMATIC
Mileage	22,605 Miles Warranted	Body Style	Hatchback	Gears	7
Fuel Type	PETROL	Keys	2	Doors	5


Tyres

NSF	HANKOOK	5.0mm
NSR	HANKOOK	5.0mm
OSF	HANKOOK	5.0mm
OSR	HANKOOK	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Cruise control
- Park assist camera
- Service indicator
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Front parking sensor
- PAS
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Heated front seat
- Rear parking sensor
- Digital radio
- Opening panoramic glass roof
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Wheel osf
Corroded
Light



2: Door osf
Chipped
Edge Chip



3: Wheel osr
Scratched
Over 50mm



4: Bumper Rear
Chipped
1 To 5



5: Wheel nsr
Scratched
Over 50mm



6: Door nsf
Chipped
Edge Chip



7: Wheel nsf
Scratched
Over 50mm



8: Bumper Front
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		