



VEHICLE INSPECTION REPORT

KD17DZC

Mazda MX-5 1.5 Sport Nav 2dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	14/07/2017	Body Style	Convertible	Last service miles	5,416
Year	2017	Keys	1	MOT Due	27/07/2027
Mileage	5,527 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Printout	Gears	6
Colour	BLUE	Number of stamps	1	Doors	2
VIN	JMZND6EA600131855	Last service date	28/07/2026		

£90 additional fee

LAST SERVICE 28/07/2026 @ 5,416 MILES (1 SERVICE) Driver side window faulty

Tyres

NSF	BUDGET	6.0mm
NSR	YOKOHAMA	5.0mm
OSF	BUDGET	6.0mm
OSR	BUDGET	6.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Steering wheel mounted controls
- Air conditioning
- Height adjustable drivers seat
- ABS
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Rear parking sensor
- Digital radio
- Front armrest
- Steering wheel rake adjustment
- Drivers airbag
- Central locking
- Heated front seat
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Steering wheel reach adjustment
- Passenger airbag
- Remote central locking
- Navigation system
- Service indicator
- Electric door mirrors
- Front head restraints
- Metallic Paint
- Traction control
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Bumper Front
Poor Previous Repair
Poor Paint



2: Bumper Rear
Poor Previous Repair
Poor Paint



3: Door osf
 Poor Previous Repair
 Rippled UpTo 30%

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	Fault	Steering	OK
Sat nav	OK		