



VEHICLE INSPECTION REPORT

WX65XUC

BMW 4 Series 435d xDrive Luxury 2dr Auto [Professional Media]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	01/09/2015	Body Style	Coupe	Last service miles	79,123
Year	2015	Keys	2	MOT Due	14/09/2027
Mileage	90,888 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	DIESEL	Service documents	Electronic & Paper	Gears	8
Colour	SILVER	Number of stamps	6	Doors	2
VIN	WBA3S92090K581024	Last service date	04/03/2025		

£100 ADDITIONAL FEE

Last Service - 04.03.25 at 79123 miles (6 services)

Mileage input error on MOT history 30.08.19

Tyres


NSF	CONTINENTAL	5.0mm
NSR	CONTINENTAL	5.0mm
OSF	CONTINENTAL	5.0mm
OSR	CONTINENTAL	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Electric door mirrors
- Electrically adjustable passenger seat
- Metallic Paint
- Traction control
- Leather seat trim
- Front parking sensor
- Telephone
- Air conditioning
- Front armrest
- ABS
- Tyre pressure monitor
- Alloy wheels
- Heated front seat
- Radio/CD
- Climate control
- Front electric windows
- Drivers airbag
- Central locking
- Navigation system
- Body coloured bumpers
- Electrically adjustable drivers seat
- Rear headrests
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Corroded
Light



2: Wing osf
Chipped
1 To 5



3: Door osf
Scratched
UpTo 25mm Thru Paint



4: Door osf
Chipped
Edge Chip



5: Wheel osr
Corroded
Light



6: Wheel nsr
Corroded
Light



7: Door nsf
Chipped
Edge Chip



8: Door nsf
Chipped
1 To 5



9: Wheel nsf
Corroded
Light




10: Wing nsf
Chipped
1 To 5




11: Bumper Front
Chipped
Multiple Chips




12: Bonnet
Chipped
1 To 5



13: Roof
Chipped
1 To 5



14: Door osf
Dented
Between 10mm + 30mm



15: Qtr Panel nsr
Dented
Between 10mm + 30mm

16: Door nsf
Dented
Between 10mm + 30mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK