



VEHICLE INSPECTION REPORT

YC66YFE

Kia Sportage 1.6 GDi 1 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Buyer To Apply



Details

Reg. date	15/10/2016	Body Style	Estate	MOT Due	03/07/2027
Year	2016	Keys	2	Gearbox	MANUAL
Mileage	121,113 Miles Not Warranted	Service history	Yes	Gears	6
Fuel Type	PETROL	Service documents	Printout	Doors	5
Colour	SILVER	Number of stamps	1		
VIN	U5YPG814LGL168416	Last service date	11/05/2021		

£100 additional fee

Last Service - 11.05.21 at unknown miles (1 service)

No V5 Oil light on

Abs and traction light on

Low clutch

Tyres

NSF	BUDGET	Damaged
NSR	NEXEN	5.0mm
OSF	LANDSAIL	5.0mm
OSR	ROYALBLACK	5.0mm
Spare		OK

Features


- Bluetooth connection
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Remote central locking
- Rear wiper
- Air conditioning
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Radio/CD
- Front armrest
- Metallic Paint
- Traction control
- Alloy wheels
- Body coloured bumpers
- Front electric windows
- ABS
- Central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Corroded
Light



2: Wing osf
Scratched
UpTo 25mm Thru Paint



3: Door osf
Chipped
1 To 5



4: Door osr
Chipped
1 To 5



5: Qtr Panel osr
Scratched
Over 25mm Thru Paint



6: Bumper Rear
Scratched
Over 100mm Thru Paint



7: Tailgate
Chipped
1 To 5



8: Wheel nsr
Scratched
Up To 50mm



9: Door nsr
Dented
With Paint Damage



10: Door nsf
Chipped
Edge Chip



11: Wing nsf
Scratched
Over 25mm Thru Paint



12: Bumper Front
Scratched
Over 100mm Thru Paint



13: Bonnet
Chipped
1 To 5



14: Carpets Front
Holed
Over 3mm



15: Door nsf
Chipped
1 To 5

16: Tyre nsf
Damaged
Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	Fault
Airbag light illuminated	Fault	Service indicator light illuminated	OK
ABS light illuminated	Fault		
Windows	OK	Radio	OK
		Steering	OK