



VEHICLE INSPECTION REPORT

ML18WHN

Honda Civic 1.0 VTEC Turbo SR 5dr

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 TBC

nama
GRADE
2

Details

Reg. date 30/04/2018

Year 2018

Mileage 53,195 Miles
Warranted

Fuel Type PETROL

Colour WHITE

VIN SHHFK6760HU022017

Body Style Hatchback

Keys 1

MOT Due 06/05/2027

Gearbox MANUAL

Gears 6

Doors 5

Acc system warning light displayed
Steering warning light displayed
Handbrake faulty

Tyres

NSF COOPER TIRES 6.0mm

NSR LAUFENN 5.0mm

OSF COOPER TIRES 6.0mm

OSR LAUFENN 5.0mm

Spare

Features


- Bluetooth connection
- Park assist camera
- Service indicator
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Cruise control
- PAS
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim
- Navigation system
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Seat Back Cover osf
Torn
Over 3mm



2: Bonnet
Chipped
1 To 5



3: Bumper Front
Chipped
1 To 5



4: Wheel nsf
Scratched
Over 50mm



5: Handle Outer nsr
Scratched (Painted)
UpTo 25mm Thru Paint



6: Wheel nsr
Scratched
Over 50mm



7: Bumper Rear
Chipped
1 To 5



8: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



9: Door osr
Chipped
Edge Chip



10: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



11: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	Fault	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK