



# VEHICLE INSPECTION REPORT

**YK64HCF**

## Vauxhall Astra Gtc 1.4T 16V 140 SRi 3dr Auto

| Inspection      |    | Vehicle |         |
|-----------------|----|---------|---------|
| Serious Damage? | No | VAT     | Margin  |
|                 |    | V5      | Present |



### Details

|           |                        |                   |              |                    |           |
|-----------|------------------------|-------------------|--------------|--------------------|-----------|
| Reg. date | 01/09/2014             | Body Style        | Hatchback    | Last service miles | 76,409    |
| Year      | 2014                   | Keys              | 2            | MOT Due            | Expired   |
| Mileage   | 87,248 Miles Warranted | Service history   | Yes          | Gearbox            | AUTOMATIC |
| Fuel Type | PETROL                 | Service documents | Service Book | Gears              | 6         |
| Colour    | RED                    | Number of stamps  | 9            | Doors              | 3         |
| VIN       | W0LPF2EC3EG086705      | Last service date | 31/08/2024   |                    |           |

MOT EXPIRED

LAST SERVICE 31/08/2024 @ 76,409 MILES (9 SERVICES, 7 MAIN DEALER)

### Tyres

|       |       |       |
|-------|-------|-------|
| NSF   | APLUS | 5.0mm |
| NSR   | APLUS | 5.0mm |
| OSF   | APLUS | 5.0mm |
| OSR   | APLUS | 5.0mm |
| Spare |       |       |

## Features


- Bluetooth connection
- Rear parking sensor
- Radio/CD
- Air conditioning
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Front parking sensor
- Service indicator
- Electric door mirrors
- Front armrest
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- PAS
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

## Photos






## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Scratched  
25 to 100mm Thru Paint



3: Wing nsf  
Dented  
2 Or Less UpTo 10mm



4: Wing nsf  
Chipped  
Multiple Chips




5: A Post ns  
Chipped  
1 To 5



6: Door Mirror Assy nsf  
Broken  
Replace



7: Door nsf  
Dented  
With Paint Damage




8: Qtr Panel nsr  
Dented  
With Paint Damage



9: Wheel nsr  
Scratched  
Over 50mm




10: Wheel nsf  
Scratched  
Up To 50mm



11: Bumper Rear  
Scratched  
Over 100mm Thru Paint



12: Tailgate  
Scratched  
Up To 25mm Thru Paint



13: Qtr Panel osr  
Dented  
With Paint Damage



14: Wheel osr  
Corroded  
Light



15: Door osf  
Scratched  
Over 25mm Thru Paint



16: Door osf  
Dented  
Between 10mm + 30mm



17: Roof  
Scratched  
Over 25mm Thru Paint



18: Wing osf  
Chipped  
Multiple Chips



19: Seat Base Cover osf  
Scuffed  
Over 25mm



20: Seat Back Cover osf  
Scuffed  
Over 25mm

## Interior

Carpet Condition  
Seat Condition

Average  
Average

Upholstery Condition  
Odour

Average  
No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

|                          |    |                                                |    |
|--------------------------|----|------------------------------------------------|----|
| Engine Runs              | OK | Gearbox 1st and Reverse Test                   | OK |
| Brakes                   | OK | Gearbox Static Gear Selection (engine running) | OK |
| Turbo Boosting           | OK | No Excessive Smoking                           | OK |
| Parking Brake            | OK |                                                |    |
| EML light illuminated    | OK | Oil warning light illuminated                  | OK |
| Airbag light illuminated | OK | Service indicator light illuminated            | OK |
| ABS light illuminated    | OK |                                                |    |
| Windows                  | OK | Radio                                          | OK |
|                          |    | Steering                                       | OK |