



VEHICLE INSPECTION REPORT

LK66KZL

Volkswagen Tiguan 2.0 TDi 150 4Motion SE 5dr DSG

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	30/11/2016	Body Style	Estate	MOT Due	03/01/2027
Year	2016	Service history	Yes	Gearbox	SEMI AUTO
Mileage	102,705 Miles Warranted	Service documents	Service Book	Gears	7
Fuel Type	DIESEL	Number of stamps	8	Doors	5
Colour	WHITE	Last service date	04/07/2025		
VIN	WVGZZZ5NZHW311754	Last service miles	77,586		

£90 ADDITIONAL FEE

CAMBELT & WATER PUMP REPLACED 14/02/2023

LAST SERVICE 04/07/2025 @ 77,586 MILES (8 SERVICES)


GEARBOX FAULT WHEN WARM AND INTERMITTENT EML LIGHT

Tyres


NSF	SUNNY	3.0mm
NSR	ACCELERA	5.0mm
OSF	SUNNY	4.0mm
OSR	ACCELERA	5.0mm
Spare		

Photos





Condition Check



Damage Photos



1: Wing of
Chipped
1 To 5



2: Wheel of
Corroded
Light



3: Wheel osr
Corroded
Light



4: Door osr
Chipped
1 To 5



5: Bumper Rear
Chipped
Multiple Chips



6: Tailgate
Chipped
1 To 5



7: Qtr Panel nsr
Dented
With Paint Damage



8: Wheel nsr
Corroded
Light



9: Door nsr
Dented
Between 10mm + 30mm



10: Door nsf
Dented
Between 10mm + 30mm




11: Wheel nsf
Corroded
Light



12: Bumper Front
Chipped
Multiple Chips



13: Bonnet
Chipped
Multiple Chips



14: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition -
Seat Condition -

Upholstery Condition -
Odour -

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK