



VEHICLE INSPECTION REPORT

RK61TZO

BMW X3 xDrive30d SE 5dr Step Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	03/09/2011	Body Style	Estate	Last service miles	89,020
Year	2011	Keys	2	MOT Due	28/05/2027
Mileage	93,320 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	DIESEL	Service documents	Service Book	Gears	8
Colour	BLUE	Number of stamps	6	Doors	5
VIN	WBAWY52090LX98801	Last service date	06/11/2025		

Last Service - 06.11.225 at 89020 miles (6 services)


Tyres

NSF	ROYALBLACK	4.0mm
NSR	ROYALBLACK	5.0mm
OSF	ROYALBLACK	4.0mm
OSR	ROYALBLACK	5.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Heated front seat
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim

Photos






Condition Check



Damage Photos



1: Door osf
Chipped
1 To 5



2: Door osf
Chipped
Edge Chip



3: Door osr
Scratched
Over 25mm Thru Paint



4: Qtr Panel osr
Poor Previous Repair
Poor Paint



5: Tailgate
Chipped
1 To 5



6: Bumper Rear
Chipped
1 To 5



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Door nsf
Chipped
Edge Chip



9: Door nsf
Chipped
1 To 5



10: Wheel nsf
Scratched
Up To 50mm



11: Bonnet
Chipped
1 To 5



12: Seat Base Cover osf
Torn
Over 3mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK