



VEHICLE INSPECTION REPORT

GU66OJH

Skoda Fabia 1.2 TSI 90 SE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	20/09/2016	Body Style	Estate	Last service miles	61,895
Year	2016	Keys	2	MOT Due	17/08/2027
Mileage	62,413 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Printout	Gears	5
Colour	SILVER	Number of stamps	8	Doors	5
VIN	TMBKM6NJ2HZ037754	Last service date	30/07/2026		

CLUTCH REPLACED 23/08/2023
TIMING BELT REPLACED 14/08/2023
WATER PUMP REPLACED 03/03/2025
LAST SERVICE 30/07/2026 @ 61,895 MILES (8 SERVICES)


Tyres

NSF	BUDGET	5.0mm
NSR	CONTINENTAL	5.0mm
OSF	CONTINENTAL	5.0mm
OSR	PIRELLI	5.0mm
Spare		

Features


- Bluetooth connection
- Telephone
- Air conditioning
- ABS
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Radio/CD
- Front electric windows
- Drivers airbag
- Central locking
- Rear parking sensor
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear wiper
- Electric door mirrors
- Metallic Paint
- Traction control
- Cloth seat trim

Photos






Condition Check



Damage Photos



1: Wing of
Dented
With Paint Damage



2: Wheel of
Scratched
Over 50mm



3: Door osf
Dented
With Paint Damage



4: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



5: A Post os
Chipped
1 To 5



6: Door osr
Chipped
1 To 5



7: Wheel osr
Scratched
Over 50mm



8: Qtr Panel osr
Chipped
1 To 5



9: Bumper Rear
Scratched
Over 100mm Thru Paint




10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Wheel nsr
Scratched
Over 50mm



12: Door nsr
Dented
With Paint Damage



13: Door nsf
Dented
With Paint Damage



14: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint




15: Wing nsf
Dented
With Paint Damage



16: Wheel nsf
Scratched
Over 50mm



17: Bumper Front
Dented
With Paint Damage



18: Bonnet
Dented
With Paint Damage

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK