



VEHICLE INSPECTION REPORT

FL13UDK

Land Rover Freelander 2.2 TD4 S 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	23/05/2013	Body Style	Estate	Last service miles	120,699
Year	2013	Keys	2	MOT Due	05/03/2027
Mileage	139,092 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	DIESEL	Service documents	Service Book	Gears	6
Colour	WHITE	Number of stamps	5	Doors	5
VIN	SALFA2CC8DH332132	Last service date	27/01/2025		

Last Service - 27.01.25 at 120699 miles (5 services)

Tyres

NSF	CONTINENTAL	3.0mm
NSR	GOODYEAR	3.0mm
OSF	CONTINENTAL	3.0mm
OSR	GOODYEAR	6.0mm
Spare		

Features


- PAS
- Telephone
- Air conditioning
- Front head restraints
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Remote central locking
- Rear parking sensor
- Radio/CD
- Climate control
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Traction control
- Cloth seat trim
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Tyre pressure monitor
- Alloy wheels
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Alarm

Photos





Condition Check



Damage Photos



1: Wing osf
Chipped
1 To 5



2: Door Mirror Assy osf
Broken
Replace



3: Door osf
Chipped
Edge Chip



4: Wheel osr
Corroded
Light



5: Door osf
Dented
Between 10mm + 30mm



6: Qtr Panel osr
Scratched
Over 25mm Thru Paint



7: Bumper Rear
Scratched
25 to 100mm Thru Paint



8: Bumper Rear
Chipped
Multiple Chips



9: Wheel nsr
Scratched
Up To 50mm



10: Door nsf
Scratched
Over 25mm Thru Paint



11: Wheel nsf
Scratched
Up To 50mm



12: Wing nsf
Scratched
UpTo 25mm Thru Paint



13: Bumper Front
Scratched
25 to 100mm Thru Paint



14: Bumper Front
Chipped
Multiple Chips



15: Bonnet
Chipped
1 To 5



16: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK