



VEHICLE INSPECTION REPORT

HN17VRM

Ford Kuga 1.5 EcoBoost 182 Titanium 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



Details

Reg. date	31/05/2017	Colour	BLUE	MOT Due	24/05/2027
Year	2017	VIN	WF0AXXWPMAHM04090	Gearbox	AUTOMATIC
Mileage	70,979 Miles Warranted	Body Style	Hatchback	Gears	6
Fuel Type	PETROL	Keys	2	Doors	5

Tyres

NSF	NEXEN	3.0mm
NSR	WESTLAKE	5.0mm
OSF	NEXEN	3.0mm
OSR	WESTLAKE	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Radio/CD
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Rear wiper
- Body coloured bumpers
- Space saver spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- PAS
- Digital radio
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Wing nsf
Chipped
1 To 5



6: Door nsf
Chipped
Multiple Chips



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Qtr Panel nsr
Dented
Between 10mm + 30mm



9: Bumper Rear
Scratched
25 to 100mm Thru Paint



10: Tailgate
Chipped
1 To 5



11: B Post os
Dented
Over 30mm



12: Qtr Panel osr
Chipped
1 To 5



13: Wheel osr
Scratched
Over 50mm



14: Door osr
Chipped
Edge Chip



15: Door osr
Chipped
1 To 5



16: Door osf
Chipped
Edge Chip



17: Wing osf
Chipped
1 To 5



18: A Post os
Scratched
Over 25mm Thru Paint



19: Roof
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK