



VEHICLE INSPECTION REPORT

LD16VTC

Kia Ceed 1.6 CRDi ISG 1 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	21/04/2016	Body Style	Hatchback	Last service miles	142,345
Year	2016	Keys	2	MOT Due	02/12/2026
Mileage	158,078 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	DIESEL	Service documents	Printout	Gears	6
Colour	SILVER	Number of stamps	1	Doors	5
VIN	U5YHM516LGL241514	Last service date	03/12/2025		

LAST SERVICE 03/12/2025 @ 142,345 MILES (1 SERVICE)


Tyres


NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	MAZZINI	5.0mm
OSR	MAZZINI	5.0mm
Spare		

Features


- Rear wiper
- Electric door mirrors
- Rear headrests
- Passenger airbag
- Remote central locking
- Telephone
- Air conditioning
- Metallic Paint
- Traction control
- Cloth seat trim
- Radio/CD
- Front armrest
- ABS
- Tyre pressure monitor
- Steel wheels
- Body coloured bumpers
- Front electric windows
- Drivers airbag
- Central locking

Photos






Condition Check



Damage Photos



1: Wing osf
Dented
Over 30mm



2: Door osf
Dented
2 Or Less UpTo 10mm




3: Door osf
Chipped
1 To 5



4: Door osr
Scratched
UpTo 25mm Thru Paint



5: Qtr Panel osr
Dented
With Paint Damage



6: Bumper Rear
Scratched
Over 100mm Thru Paint



7: Qtr Panel nsr
Dented
With Paint Damage




8: Door nsr
Scratched
UpTo 25mm Thru Paint



9: Wing nsf
Chipped
Multiple Chips



10: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



11: Bumper Front
Scratched
Over 100mm Thru Paint



12: Bonnet
Chipped
Multiple Chips



13: Screen Front
Chipped
UpTo 10mm



14: B Post os
Dented
With Paint Damage



15: C Post os
Dented
With Paint Damage

16: C Post ns
Dented
With Paint Damage



17: B Post ns
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
		Steering	OK