



VEHICLE INSPECTION REPORT

EX13YBG

Nissan Qashqai 1.6 [117] 360 5dr CVT

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	25/03/2013	Body Style	Hatchback	Last service miles	129,017
Year	2013	Keys	1	MOT Due	31/07/2027
Mileage	129,831 Miles Warranted	Service history	Yes	Gearbox	CVT
Fuel Type	PETROL	Service documents	Printout	Gears	1
Colour	BLACK	Number of stamps	2	Doors	5
VIN	SJNFAAJ10U2760045	Last service date	13/07/2026		

Last Service - 13.07.26 at 129017 miles (2 services) gearbox fault

Tyres


NSF	SAILUN	4.0mm
NSR	NEXEN	6.0mm
OSF	SAILUN	4.0mm
OSR	NEXEN	6.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Cruise control
- Telephone
- Fixed panoramic glass roof
- Front electric windows
- ABS
- Central locking
- Alloy wheels
- Park assist camera
- Radio/CD
- Air conditioning
- Rear electric windows
- Drivers airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Rear headrests
- Passenger airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Seat Base Cover osf
Torn
Over 3mm



2: Wheel osf
Corroded
Light



3: Wing osf
Chipped
1 To 5



4: Door osf
Chipped
Multiple Chips



5: Door osr
Dented
Over 30mm



6: Wheel osr
Corroded
Light



7: Bumper Rear
Poor Previous Repair
Paint Flake



8: Lamp osr
Broken
Replace



9: Tailgate
Dented
With Paint Damage



10: Wheel nsr
Corroded
Light



11: Door nsr
Dented
With Paint Damage



12: Door nsf
Dented
With Paint Damage



13: Door Mirror Assy nsf
Broken
Replace



14: Wing nsf
Dented
With Paint Damage




15: Wheel nsf
Corroded
Light



16: Bumper Front
Scratched
Over 100mm Thru Paint



17: Bonnet
Chipped
1 To 5



18: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	Fault
Brakes	OK	Clutch Slip Test from Static	Fault
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	Fault
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK