



# VEHICLE INSPECTION REPORT

**GU17LYW**

## Suzuki Ignis 1.2 Dualjet SZ3 5dr

| Inspection      |    | Vehicle |         |
|-----------------|----|---------|---------|
| Serious Damage? | No | VAT     | Margin  |
|                 |    | V5      | Present |



### Details

|           |                           |                   |              |                    |         |
|-----------|---------------------------|-------------------|--------------|--------------------|---------|
| Reg. date | 09/03/2017                | Body Style        | Hatchback    | Last service miles | 28,337  |
| Year      | 2017                      | Keys              | 2            | MOT Due            | Expired |
| Mileage   | 37,006 Miles<br>Warranted | Service history   | Yes          | Gearbox            | MANUAL  |
| Fuel Type | Petrol                    | Service documents | Service Book | Gears              | 5       |
| Colour    | RED/BLACK                 | Number of stamps  | 6            | Doors              | 5       |
| VIN       | JSAMFH11S00101973         | Last service date | 28/04/2023   |                    |         |

Last service 28/04/2023 @ 28337 miles (6 SERVICES 5 MAIN DEALER)

### Tyres


|       |        |       |
|-------|--------|-------|
| NSF   | NEXEN  | 4.0mm |
| NSR   | NEXEN  | 4.0mm |
| OSF   | BUDGET | 3.0mm |
| OSR   | NEXEN  | 4.0mm |
| Spare |        |       |

## Features


- Bluetooth connection
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- ABS
- Side airbags
- Cloth seat trim
- PAS
- Radio/CD
- Climate control
- Rear headrests
- Drivers airbag
- Traction control
- Steel wheels
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Solid Paint
- Isofix child seat anchor points
- Central locking
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Scratched  
Over 100mm Thru Paint





3: Wing nsf  
Scratched  
UpTo 25mm Thru Paint



4: Door nsf  
Chipped  
1 To 5




5: Door nsr  
Chipped  
1 To 5



6: Qtr Panel nsr  
Dented  
2 Or Less UpTo 10mm



7: Bumper Rear  
Chipped  
Multiple Chips



8: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint



9: Boot Lid  
Chipped  
1 To 5




10: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



11: Door osr  
Chipped  
1 To 5



12: Door osf  
Dented  
With Paint Damage



13: Wing osf  
Scratched  
Over 25mm Not Thru Paint

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

|                          |    |  |       |
|--------------------------|----|--|-------|
| Engine Runs              | OK | Gearbox 1st and Reverse Test                   | OK    |
| Brakes                   | OK | Clutch Slip Test from Static                   | OK    |
| Parking Brake            | OK | Gearbox Static Gear Selection (engine running) | OK    |
|                          |    | No Excessive Smoking                           | OK    |
| EML light illuminated    | OK | Oil warning light illuminated                  | OK    |
| Airbag light illuminated | OK | Service indicator light illuminated            | Fault |
| ABS light illuminated    | OK |  |       |
| Windows                  | OK | Radio  | OK    |
|                          |    | Steering                                       | OK    |