



VEHICLE INSPECTION REPORT

GD19GKC

Volkswagen Golf 1.6 TDI Match 5dr DSG

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	06/06/2019	Body Style	Hatchback	Last service miles	38,782
Year	2019	Keys	2	MOT Due	29/06/2027
Mileage	40,182 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	DIESEL	Service documents	Printout	Gears	6
Colour	SILVER	Number of stamps	2	Doors	5
VIN	WVVZZZAUZKW147982	Last service date	03/03/2026		

LAST SERVICE 03/03/2026 @ 38,782 MILES (2 SERVICE)


Tyres



NSF	BRIDGESTONE	5.0mm
NSR	BRIDGESTONE	5.0mm
OSF	BRIDGESTONE	5.0mm
OSR	BRIDGESTONE	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Central locking
- Front parking sensor
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Navigation system
- Radio/CD
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Wing osf
Dented
With Paint Damage



2: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



3: Door osf
Chipped
1 To 5



4: Door osf
Chipped
Edge Chip




5: Qtr Panel osr
Poor Previous Repair
Poor Paint



6: Door osr
Poor Previous Repair
Poor Paint



7: Wheel osr
Scratched
Up To 50mm



8: Bumper Rear
Chipped
1 To 5



9: Qtr Panel nsr
Chipped
1 To 5



10: Door nsr
Chipped
1 To 5



11: Door nsf
Chipped
1 To 5



12: Wing nsf
Poor Previous Repair
Poor Paint



13: Bumper Front
Scratched
Over 100mm Thru Paint



14: Roof
Dented
With Paint Damage

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK