



VEHICLE INSPECTION REPORT

GY23NZV

Volkswagen Taigo 1.0 TSI 110 Style 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	22/03/2023	Body Style	Hatchback	Last service miles	23,779
Year	2023	Keys	2	MOT Due	21/03/2027
Mileage	26,947 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Printout	Gears	6
Colour	GREY	Number of stamps	3	Doors	5
VIN	WVGZZZCSZPY040217	Last service date	05/03/2026		

£90 ADDITIONAL FEE

Last Service - 05.03.26 at 23779 miles (3 main dealer services)

Tyres


NSF	KUMHO	6.0mm
NSR	GOODYEAR	5.0mm
OSF	KUMHO	6.0mm
OSR	GOODYEAR	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Digital radio
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check




Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
1 To 5



3: Bumper Rear
Scratched
Up To 25mm Thru Paint

4: Door osr
Chipped
1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK