



# VEHICLE INSPECTION REPORT

**KN70AED**

## Seat Arona 1.0 TSI SE Technology [EZ] 5dr

| Inspection      |    | Vehicle |         |
|-----------------|----|---------|---------|
| Serious Damage? | No | VAT     | Margin  |
|                 |    | V5      | Present |

nama  
GRADE  
**3**

### Details

|           |                           |                   |            |                    |            |
|-----------|---------------------------|-------------------|------------|--------------------|------------|
| Reg. date | 01/09/2020                | Body Style        | Hatchback  | Last service miles | 46,247     |
| Year      | 2020                      | Keys              | 2          | MOT Due            | 31/08/2027 |
| Mileage   | 46,434 Miles<br>Warranted | Service history   | Yes        | Gearbox            | MANUAL     |
| Fuel Type | PETROL                    | Service documents | Printout   | Gears              | 5          |
| Colour    | BLACK                     | Number of stamps  | 3          | Doors              | 5          |
| VIN       | VSSZZZKJZLR157090         | Last service date | 22/08/2026 |                    |            |

£90 ADDITIONAL FEE

LAST SERVICE 22/08/2026 @ 46,247 MILES (3 SERVICES) Breather pipe split

### Tyres


|       |             |       |
|-------|-------------|-------|
| NSF   | PIRELLI     | 5.0mm |
| NSR   | PIRELLI     | 5.0mm |
| OSF   | PIRELLI     | 5.0mm |
| OSR   | CONTINENTAL | 5.0mm |
| Spare |             |       |

## Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- PAS
- Digital radio
- Roof rails
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Chipped  
1 To 5



3: Wheel nsf  
Scratched  
Over 50mm



4: Door nsf  
Dented  
Between 10mm + 30mm



5: Door nsr  
Chipped  
1 To 5



6: Door nsr  
Dented  
Between 10mm + 30mm



7: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



8: Qtr Panel osr  
Scratched  
UpTo 25mm Thru Paint



9: Door osr  
Dented  
Over 30mm



10: Door osf  
Dented  
Over 2 UpTo 10mm



11: Wing osf  
Dented  
Between 10mm + 30mm

### Interior

|                  |         |                      |         |
|------------------|---------|----------------------|---------|
| Carpet Condition | Average | Upholstery Condition | Average |
| Seat Condition   | Average | Odour                | No      |

### Vehicle Inspection Report

**Disclaimer**  
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
 Additional fees may apply to some vendors.  
 Please note buyers rate increase from 01/01/2025

|               |    |                                                |    |
|---------------|----|------------------------------------------------|----|
| Engine Runs   | OK | Gearbox 1st and Reverse Test                   | OK |
| Brakes        | OK | Clutch Slip Test from Static                   | OK |
| Parking Brake | OK | Gearbox Static Gear Selection (engine running) | OK |
|               |    | No Excessive Smoking                           | OK |

|                          |    |                                     |    |
|--------------------------|----|-------------------------------------|----|
| EML light illuminated    | OK | Oil warning light illuminated       | OK |
| Airbag light illuminated | OK | Service indicator light illuminated | OK |
| ABS light illuminated    | OK |                                     |    |
| Windows                  | OK | Radio                               | OK |
| Sat nav                  | OK | Steering                            | OK |