



VEHICLE INSPECTION REPORT

EJ11FTX

Ford Focus 1.6 125 Zetec 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	28/04/2011	Body Style	Hatchback	Last service miles	33,890
Year	2011	Keys	2	MOT Due	01/12/2026
Mileage	94,068 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	5
Colour	WHITE	Number of stamps	5	Doors	5
VIN	WF0KXXGCBKBE48926	Last service date	14/03/2016		

Last Service - 14.03.16 at 33890 miles (5 services) Exhaust blowing
Intermittent misfire


Tyres

NSF	SUNNY	6.0mm
NSR	BUDGET	5.0mm
OSF	SUNNY	6.0mm
OSR	SUNNY	5.0mm
Spare		

Features


- Bluetooth connection
- Body coloured bumpers
- Front electric windows
- Drivers airbag
- Remote central locking
- Rear wiper
- Electric door mirrors
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Telephone
- Air conditioning
- Solid Paint
- Traction control
- Alloy wheels
- Radio/CD
- Front armrest
- ABS
- Central locking

Photos






Condition Check




Damage Photos



1: Wheel osf
Scratched
Over 50mm




2: Wing osf
Dented
With Paint Damage



3: Door osf
Dented
Over 30mm



4: Door osr
Dented
With Paint Damage




5: Qtr Panel osr
Dented
With Paint Damage



6: Bumper Rear
Poor Previous Repair
Paint Flake



7: Tailgate
Rusted
Over 5mm



8: Qtr Panel nsr
Dented
With Paint Damage



9: Wheel nsr
Scratched
Up To 50mm



10: Door nsr
Scratched
Over 25mm Thru Paint




11: Wheel nsf
Scratched
Up To 50mm



12: Wing nsf
Scratched
Over 25mm Thru Paint



13: Bumper Front
Scratched
Over 100mm Thru Paint



14: Other
N/A
N/A



15: Other
N/A
N/A



16: Bonnet
Chipped
1 To 5



17: Roof
Chipped
1 To 5



18: Seat Back Cover osf
Holed
UpTo 3mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK