

VEHICLE INSPECTION REPORT

GX16FPL

Honda HR-V 1.5 i-VTEC SE 5dr

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 TBC

nama
GRADE
2

Details

Reg. date	01/03/2016	Colour	WHITE	MOT Due	28/02/2027
Year	2016	VIN	3HGRU1750GM301071	Gearbox	MANUAL
Mileage	59,254 Miles Warranted	Body Style	Hatchback	Gears	6
Fuel Type	PETROL	Keys	2	Doors	5

Tyres

NSF	FALKEN	6.0mm
NSR	FALKEN	6.0mm
OSF	FALKEN	6.0mm
OSR	MICHELIN	5.0mm

Spare

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Cruise control
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Front parking sensor
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
1 To 5



3: Wheel nsf
Scratched
Over 50mm




4: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint




5: Door nsf
Chipped
Edge Chip



6: Qtr Panel Arch Extension ns
Scuffed (Unpainted)
UpTo 100mm



7: Wheel nsr
Scratched
Over 50mm



8: Wheel osr
Scratched
Over 50mm



9: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



10: Door osf
Chipped
Edge Chip



11: Wheel osf
Scratched
Over 50mm



12: Wing osf
Chipped
1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK