



VEHICLE INSPECTION REPORT

GU59LFJ

Ford Focus 1.8 Zetec 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	07/12/2009	Body Style	Hatchback	Last service miles	73,706
Year	2009	Keys	2	MOT Due	09/12/2026
Mileage	77,771 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	5
Colour	GREY	Number of stamps	10	Doors	5
VIN	WF0PXXWDP9C40976	Last service date	27/11/2024		

Last Service - 27.11.2024 at 73706 miles (10 Services) Car vibrates on idle
High clutch


Tyres

NSF	HANKOOK	6.0mm
NSR	HANKOOK	6.0mm
OSF	HANKOOK	6.0mm
OSR	HANKOOK	6.0mm
Spare		

Features


- Bluetooth connection
- Body coloured bumpers
- Front electric windows
- Drivers airbag
- Remote central locking
- Rear wiper
- Electric door mirrors
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Telephone
- Air conditioning
- Metallic Paint
- Traction control
- Alloy wheels
- Radio/CD
- Front armrest
- ABS
- Central locking

Photos






Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Poor Previous Repair
Poor Paint



3: Door osf
Scratched
Over 25mm Thru Paint



4: Door osr
Scratched
Over 25mm Thru Paint



5: Qtr Panel osr
Scratched
Over 25mm Thru Paint



6: Wheel osr
Scratched
Over 50mm



7: Bumper Rear
Chipped
Multiple Chips



8: Bumper Rear
Scratched
Up To 25mm Thru Paint



9: Other
N/A
N/A



10: Qtr Panel nsr
Chipped
1 To 5



11: Door nsr
Chipped
1 To 5



12: Door nsf
Poor Previous Repair
Poor Paint



13: Bumper Front
Scratched
Over 100mm Thru Paint



14: Bonnet
Poor Previous Repair
Poor Paint



15: Screen Front
Chipped
UpTo 10mm



16: C Post os
Dented
Between 10mm + 30mm



17: Seat Base Cover osf
Holed
UpTo 3mm



18: Roof
Dented
Hail - Moderate

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK