



# VEHICLE INSPECTION REPORT

**EO62ZFS**

## Seat MII 1.0 SE 5dr

| Inspection      |    | Vehicle |                |
|-----------------|----|---------|----------------|
| Serious Damage? | No | VAT     | Margin         |
|                 |    | V5      | Buyer To Apply |



### Details

|            |                            |                    |              |             |           |
|------------|----------------------------|--------------------|--------------|-------------|-----------|
| Reg. date  | 22/09/2012                 | Service history    | Yes          | CAP Average | £1,225.00 |
| Year       | 2012                       | Service documents  | Service Book | CAP Below   | £825.00   |
| Mileage    | 108,751 Miles<br>Warranted | Number of stamps   | 6            | Gearbox     | MANUAL    |
| Fuel Type  | PETROL                     | Last service date  | 11/09/2018   | Gears       | 5         |
| Colour     | WHITE                      | Last service miles | 13,374       | Doors       | 5         |
| VIN        | VSSZZZAAZDD308750          | MOT Due            | Expired      |             |           |
| Body Style | Hatchback                  | CAP Clean          | £1,625.00    |             |           |

NO V5  
MOT EXPIRED  
LAST SERVICE 11/09/2018 @ 13,374 MILES (6 SERVICES)



| Tyres |          |       |
|-------|----------|-------|
| NSF   | BUDGET   | 6.0mm |
| NSR   | MICHELIN | 5.0mm |
| OSF   | BUDGET   | 6.0mm |
| OSR   | BUDGET   | 5.0mm |
| Spare |          |       |

## Features


- PAS
- Electric door mirrors
- Front electric windows
- Steering wheel reach adjustment
- Isofix child seat anchor points
- Remote central locking
- Rear wiper
- Front fog lights
- Front head restraints
- Metallic Paint
- Passenger airbag
- Cloth seat trim
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- ABS
- Side airbags
- Alloy wheels
- Body coloured bumpers
- Climate control
- Steering wheel rake adjustment
- Drivers airbag
- Alarm

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Dented  
With Paint Damage



2: Bumper Front  
Dented  
With Paint Damage



3: Wheel osf  
Scratched  
Up To 50mm



4: Door Mirror Assy nsf  
Broken  
Replace



5: Door nsf  
Chipped  
Edge Chip



6: Door nsr  
Scratched  
Over 25mm Thru Paint



7: Bumper Rear  
Dented  
With Paint Damage



8: Qtr Panel osr  
Dented  
With Paint Damage



9: Wheel osf  
Scratched  
Over 50mm



10: Door osf  
Scratched  
Over 25mm Thru Paint



11: Door osf  
Dented  
With Paint Damage



12: Wheel osf  
Scratched  
Over 50mm



13: Wing osf  
Chipped  
1 To 5



14: Roof  
Chipped  
Edge Chip

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

|                          |    |                                                |    |
|--------------------------|----|------------------------------------------------|----|
| Engine Runs              | OK | Gearbox 1st and Reverse Test                   | OK |
| Brakes                   | OK | Clutch Slip Test from Static                   | OK |
| Parking Brake            | OK | Gearbox Static Gear Selection (engine running) | OK |
|                          |    | No Excessive Smoking                           | OK |
| EML light illuminated    | OK | Oil warning light illuminated                  | OK |
| Airbag light illuminated | OK | Service indicator light illuminated            | OK |
| ABS light illuminated    | OK |                                                |    |
| Windows                  | OK | Radio                                          | OK |
|                          |    | Steering                                       | OK |