



# VEHICLE INSPECTION REPORT

**YF15KTD**

## Volkswagen Golf 1.6 TDI 105 Match 5dr DSG

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	15/05/2015	Keys	2	CAP Clean	£6,275.00
Year	2015	Service history	Yes	CAP Average	£5,475.00
Mileage	60,421 Miles Warranted	Service documents	Service Book	CAP Below	£4,650.00
Fuel Type	Diesel	Number of stamps	7	Gearbox	SEMI AUTO
Colour	BLACK	Last service date	05/11/2024	Gears	7
VIN	WVWZZZAUZFP089054	Last service miles	54,981	Doors	5
Body Style	Hatchback	MOT Due	14/11/2025		

Last Service: 05/11/2024 at 54981 miles. (7 services (6 main dealer) )

### Tyres

NSF	ROADSTONE	4.0mm
NSR	CONTINENTAL	3.0mm
OSF	ROADSTONE	4.0mm
OSR	CONTINENTAL	3.0mm
Spare		

## Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Central locking
- Front parking sensor
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Navigation system
- Radio/CD
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim

## Photos





## Condition Check



## Damage Photos



1: Wheel osf  
Scratched  
Over 50mm



2: Wing osf  
Chipped  
1 To 5





3: Door osf  
Chipped  
Edge Chip



4: Door osr  
Scratched  
UpTo 25mm Not Thru Paint



5: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint



6: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



7: Qtr Panel nsr  
Chipped  
1 To 5



8: Wheel nsr  
Scratched  
Up To 50mm





9: Door nsr  
Scratched  
Over 25mm Not Thru Paint



10: Door nsf  
Chipped  
1 To 5



11: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



12: Wheel nsf  
Scratched  
Over 50mm



13: Bumper Front  
Scratched  
UpTo 25mm Thru Paint



14: Bonnet  
Chipped  
1 To 5

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK