



# VEHICLE INSPECTION REPORT

**KP21BLZ**

## Jaguar F-Pace 2.0 D200 R-Dynamic HSE 5dr Auto AWD

### Inspection

Serious Damage? No

### Vehicle

VAT Margin

V5 Present

nama  
GRADE  
2

### Details

|           |                        |                   |            |                    |            |
|-----------|------------------------|-------------------|------------|--------------------|------------|
| Reg. date | 10/03/2021             | Body Style        | Estate     | Last service miles | 40,901     |
| Year      | 2021                   | Keys              | 2          | MOT Due            | 26/08/2027 |
| Mileage   | 40,999 Miles Warranted | Service history   | Yes        | Gearbox            | AUTOMATIC  |
| Fuel Type | DIESEL                 | Service documents | Printout   | Gears              | 8          |
| Colour    | BLUE                   | Number of stamps  | 3          | Doors              | 5          |
| VIN       | SADCA2AN1MA670385      | Last service date | 16/03/2026 |                    |            |

LAST SERVICE 16/03/2026 @ 40,901 MILES (3 SERVICES)

### Tyres


|       |             |       |
|-------|-------------|-------|
| NSF   | CONTINENTAL | 5.0mm |
| NSR   | CONTINENTAL | 6.0mm |
| OSF   | CONTINENTAL | 5.0mm |
| OSR   | CONTINENTAL | 5.0mm |
| Spare |             |       |

## Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Rear electric windows
- Drivers airbag
- Central locking
- Navigation system
- Telephone
- Fixed panoramic glass roof
- Electrically adjustable passenger seat
- Rear headrests
- Passenger airbag
- Remote central locking
- Park assist camera
- Radio/CD
- Air conditioning
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim

## Photos





## Condition Check




## Damage Photos




1: Door osf  
Chipped  
1 To 5



2: Door osf  
Chipped  
Edge Chip



3: Door nsr  
Chipped  
Edge Chip



4: Door nsr  
Chipped  
1 To 5



5: Bumper Front  
Chipped  
Multiple Chips



6: Bumper Front  
Scratched  
25 to 100mm Thru Paint



7: Bonnet  
Chipped  
1 To 5



8: Roof  
Chipped  
1 To 5

## Interior

Carpet Condition  
Seat Condition

Average  
Average

Upholstery Condition  
Odour

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

|                          |    |                                                |    |
|--------------------------|----|------------------------------------------------|----|
| Engine Runs              | OK | Gearbox 1st and Reverse Test                   | OK |
| Brakes                   | OK | Clutch Slip Test from Static                   | OK |
| Turbo Boosting           | OK | Gearbox Static Gear Selection (engine running) | OK |
| Parking Brake            | OK | No Excessive Smoking                           | OK |
| EML light illuminated    | OK | Oil warning light illuminated                  | OK |
| Airbag light illuminated | OK | DPF light illuminated                          | OK |
| ABS light illuminated    | OK | Service indicator light illuminated            | OK |
| Roof / sunroof           | OK | Radio                                          | OK |
| Windows                  | OK | Steering                                       | OK |
| Sat nav                  | OK |                                                |    |