



VEHICLE INSPECTION REPORT

GP21DTX

Volkswagen Polo 1.0 TSI 95 Match 5dr DSG

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	15/07/2021	Body Style	Hatchback	Last service miles	12,782
Year	2021	Keys	2	MOT Due	11/06/2027
Mileage	13,287 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	PETROL	Service documents	Printout	Gears	7
Colour	BLACK	Number of stamps	5	Doors	5
VIN	WWWZZZAWZMU052919	Last service date	17/07/2026		

£90 ADDITIONAL FEE

LAST SERVICE 17/07/2026 @ 12,782 (5 SERVICES)



Tyres

NSF	FALKEN	4.0mm
NSR	GOODYEAR	5.0mm
OSF	GOODYEAR	4.0mm
OSR	GOODYEAR	5.0mm
Spare		

Features


- Bluetooth connection
- Telephone
- Air conditioning
- Metallic Paint
- Traction control
- Cloth seat trim
- Front parking sensor
- Radio/CD
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Rear parking sensor
- Body coloured bumpers
- Rear electric windows
- Drivers airbag
- Central locking
- Rear wiper
- Electric door mirrors
- Rear headrests
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Corroded
Light



2: Wing osf
Poor Previous Repair
Poor Paint



3: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



4: Door osf
Poor Previous Repair
Poor Paint



5: Door osr
Poor Previous Repair
Poor Paint



6: Wheel osr
Corroded
Light



7: Qtr Panel osr
Chipped
1 To 5



8: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



9: Bumper Rear
Poor Previous Repair
Poor Paint




10: Qtr Panel nsr
Poor Previous Repair
Poor Paint



11: Door nsr
Poor Previous Repair
Poor Paint



12: Wheel nsr
Corroded
Light



13: Door nsf
Poor Previous Repair
Poor Paint



14: Wing nsf
Poor Previous Repair
Poor Paint



15: Bumper Front
Poor Previous Repair
Poor Paint



16: Wheel nsf
Corroded
Light



17: Bonnet
Chipped
1 To 5

Interior

Carpet Condition OK
Seat Condition OK

Upholstery Condition OK
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK