



VEHICLE INSPECTION REPORT

KP120CJ

Mercedes-Benz B Class B180 BlueEFFICIENCY Sport 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	24/04/2012	Body Style	MPV	MOT Due	23/04/2027
Year	2012	Keys	2	Gearbox	AUTOMATIC
Mileage	49,793 Miles Warranted	Service history	Yes	Gears	7
Fuel Type	PETROL	Number of stamps	3	Doors	5
Colour	GREY	Last service date	27/01/2026		
VIN	WDD2462422J040231	Last service miles	49,139		

£90 additional fee


Tyres

NSF	MICHELIN	5.0mm
NSR	MICHELIN	5.0mm
OSF	MICHELIN	5.0mm
OSR	MICHELIN	5.0mm
Spare		

Features


- Bluetooth connection
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Remote central locking
- Cruise control
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Leather seat trim
- Park assist camera
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Door osf
Chipped
1 To 5



3: Door osf
Chipped
Edge Chip



4: Wheel osr
Scratched
Over 50mm



5: Bumper Rear
Scratched
Over 100mm Thru Paint



6: Bumper Rear Moulding
Missing
Replace



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint




8: Wheel nsr
Scratched
Over 50mm



9: Door nsr
Chipped
1 To 5



10: Door nsf
Chipped
Edge Chip



11: Door nsf
Scratched
UpTo 25mm Thru Paint



12: Door nsf
Chipped
1 To 5



13: Wheel nsf
Scratched
Over 50mm



14: Bumper Front
Scratched
Over 100mm Thru Paint



15: Bonnet
Chipped
1 To 5

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK