



VEHICLE INSPECTION REPORT

AD59XSG

Volkswagen Golf 1.6 TDi 105 S 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	18/01/2010	Body Style	Hatchback	Last service miles	32,310
Year	2010	Keys	2	MOT Due	30/01/2027
Mileage	92,525 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	DIESEL	Service documents	Printout	Gears	5
Colour	BLACK	Number of stamps	5	Doors	5
VIN	WVVZZZ1KZAW205370	Last service date	17/07/2014		

£90 ADDITIONAL FEE

LAST SERVICE 17/01/2014 @ 32,310 MILES (5 SERVICES)

Tyres

NSF	BUDGET	Damaged
NSR	LAUFENN	5.0mm
OSF	LAUFENN	3.0mm
OSR	CONTINENTAL	Damaged
Spare		

Features


- Rear wiper
- Air conditioning
- Solid Paint
- Traction control
- Steel wheels
- Radio/CD
- Climate control
- ABS
- Central locking
- Body coloured bumpers
- Front electric windows
- Drivers airbag
- Remote central locking
- Electric door mirrors
- Rear headrests
- Passenger airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Thru Paint



2: Door osf
Scratched
Over 25mm Thru Paint



3: Door osr
Scratched
Over 25mm Thru Paint



4: Qtr Panel osr
Dented
With Paint Damage



5: Sill os
Scratched
Over 25mm Thru Paint



6: Bumper Rear
Scratched
Over 100mm Thru Paint



7: Qtr Panel nsr
Dented
Between 10mm + 30mm



8: Qtr Panel nsr
Chipped
1 To 5



9: Door nsf
Chipped
Multiple Chips



10: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



11: Wing nsf
Dented
With Paint Damage



12: Bumper Front
Scratched
Over 100mm Thru Paint



13: Bonnet
Poor Previous Repair
Poor Paint



14: Tyre nsf
Damaged
Replace



15: Tyre osr
Damaged
Replace

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	Fault	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
		Steering	OK