



VEHICLE INSPECTION REPORT

KS14KVT

Seat Leon 1.2 TSI SE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	03/06/2014	Body Style	Hatchback	Last service miles	88,406
Year	2014	Keys	1	MOT Due	22/01/2027
Mileage	104,365 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Printout	Gears	6
Colour	RED	Number of stamps	1	Doors	5
VIN	VSSZZZ5FZER109332	Last service date	02/07/2024		

Last Service - 02.07.24 at 88406 miles (1 service) No reverse
Check oil message displays on start up

Tyres

NSF	RIKEN	5.0mm
NSR	YOKOHAMA	5.0mm
OSF	RIKEN	4.0mm
OSR	RIKEN	Damaged
Spare		

Features


- Bluetooth connection
- Radio/CD
- Front armrest
- Solid Paint
- Traction control
- Cloth seat trim
- Cruise control
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Central locking
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking

Photos






Condition Check



Damage Photos



1: Wing osf
Chipped
1 To 5



2: Door osf
Poor Previous Repair
Paint Flake



3: Door osr
Dented
With Paint Damage



4: Sill os
Dented
With Paint Damage



5: Bumper Rear
Scratched
Over 100mm Thru Paint



6: Qtr Panel nsr
Dented
With Paint Damage



7: Door nsr
Scratched
Over 25mm Thru Paint




8: Door nsf
Chipped
1 To 5



9: Door nsf
Chipped
Edge Chip



10: Other
N/A
N/A



11: Sill ns
Dented
Over 30mm




12: Wing nsf
Poor Previous Repair
Paint Flake



13: Wheel nsf
Scratched
Over 50mm




14: Bumper Front
Scratched
Over 100mm Thru Paint



15: Bonnet
Poor Previous Repair
Paint Flake



16: Wheel osr
Scratched
Over 50mm



17: Carpets Front
Holed
Over 3mm



18: Tyre osr
Damaged
Replace

Interior

Carpet Condition Poor
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	Fault
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK