



VEHICLE INSPECTION REPORT

WG19ZJY

Kia Sportage 1.6 GDi ISG 2 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	27/04/2019	VIN	U5YPH814LKL694657	Gearbox	MANUAL
Year	2019	Body Style	Estate	Gears	6
Mileage	135,843 Miles Warranted	Keys	2	Doors	5
Fuel Type	PETROL	Service history	None		
Colour	SILVER	MOT Due	09/06/2027		

NO SERVICE HISTORY

Tyres

NSF	CONTINENTAL	3.0mm
NSR	BUDGET	5.0mm
OSF	CONTINENTAL	3.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- PAS
- Digital radio
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Navigation system
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wing nsf
Scratched
Over 25mm Thru Paint



4: Door nsf
Chipped
Edge Chip



5: Door nsr
Chipped
1 To 5



6: Qtr Panel nsr
Dented
Between 10mm + 30mm



7: Tailgate
Scratched
Over 25mm Thru Paint



8: Qtr Panel osr
Chipped
1 To 5



9: Qtr Panel osr
Scratched
Over 25mm Thru Paint



10: Door osr
Scratched
Over 25mm Thru Paint



11: Door osf
Chipped
Edge Chip



12: Wing osf
Scratched
Over 25mm Thru Paint



13: A Post os
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK