



VEHICLE INSPECTION REPORT

GV72ECX

Audi A1 30 TFSI 110 Sport 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Photocopy

nama
GRADE
3

Details

Reg. date	28/01/2023	Keys	2	CAP Clean	£11,250.00
Year	2023	Service history	Yes	CAP Average	£10,150.00
Mileage	63,627 Miles Warranted	Service documents	Printout	CAP Below	£9,100.00
Fuel Type	PETROL	Number of stamps	3	Gearbox	MANUAL
Colour	BLUE	Last service date	22/01/2026	Gears	6
VIN	WAUZZZGB3PR027009	Last service miles	52,628	Doors	5
Body Style	Hatchback	MOT Due	27/01/2027		

£90 ADDITIONAL FEE

Last Service - 22.01.26 at 52628 miles (3 main dealer services)


Tyres

NSF	NEXEN	5.0mm
NSR	KUMHO	5.0mm
OSF	NEXEN	5.0mm
OSR	KUMHO	5.0mm
Spare		

Features


- Bluetooth connection
- Telephone
- Air conditioning
- Metallic Paint
- Traction control
- Cloth seat trim
- Cruise control
- Radio/CD
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Rear parking sensor
- Body coloured bumpers
- Rear electric windows
- Drivers airbag
- Central locking
- Rear wiper
- Electric door mirrors
- Rear headrests
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Wing of
Dented
With Paint Damage



2: Door of
Chipped
1 To 5



3: Qtr Panel osr
Dented
Between 10mm + 30mm



4: Door nsr
Chipped
1 To 5



5: Door nsr
Dented
2 Or Less UpTo 10mm



6: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



7: Door nsf
Dented
Between 10mm + 30mm



8: Wing nsf
Chipped
1 To 5



9: Wheel nsf
Scratched
Over 50mm



10: Bumper Front
Scratched
25 to 100mm Thru Paint



11: Bumper Front
Chipped
Multiple Chips



12: Bonnet
Chipped
1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK