



VEHICLE INSPECTION REPORT

OE16YUB

Mercedes-Benz C Class C350e Sport 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	10/08/2016	Body Style	Estate	MOT Due	09/08/2027
Year	2016	Keys	2	Gearbox	AUTOMATIC
Mileage	108,702 Miles Warranted	Service history	Yes	Gears	7
Fuel Type	HYBRID ELECTRIC	Service documents	Printout	Doors	5
Colour	BLUE	Number of stamps	2		
VIN	WDD2052472F408571	Last service date	10/03/2026		

£90 ADDITIONAL FEE

Last Service - 10.03.26 at unknown miles (2 services) EML light is on car has been plugged in and detects transmission fluid pressure sensor switch a circuit
Type 2 and 3 pin charging cables

Tyres


NSF	FALKEN	6.0mm
NSR	ROYALBLACK	6.0mm
OSF	FALKEN	6.0mm
OSR	COMFORSER	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Cruise control
- Park assist camera
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Wheel of
Scratched
Over 50mm



2: Wing of
Chipped
1 To 5



3: Wheel osr
Scratched
Over 50mm



4: Wheel nsr
Scratched
Over 50mm



5: Wheel nsf
Scratched
Over 50mm



6: Door osf
Chipped
1 To 5




7: Door osr
Chipped
Multiple Chips



8: Qtr Panel osr
Scratched
Over 25mm Thru Paint



9: Bumper Rear
Scratched
Over 100mm Thru Paint



10: Tailgate
Chipped
1 To 5



11: Fuel Flap
Missing
Replace



12: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



13: Door nsr
Chipped
1 To 5



14: Door nsf
Chipped
1 To 5



15: Door nsf
Chipped
Edge Chip




16: Door Mirror Assy nsf
Broken
Replace




17: Wing nsf
Chipped
1 To 5



18: Bumper Front
Chipped
Multiple Chips



19: Bonnet
Chipped
1 To 5



20: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK