



VEHICLE INSPECTION REPORT

LC68OCH

Citroen C3 1.2 PureTech 82 Flair Nav Edition 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	31/12/2018	Body Style	Hatchback	Last service miles	34,441
Year	2018	Keys	2	MOT Due	30/12/2026
Mileage	40,115 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	5
Colour	BLACK	Number of stamps	6	Doors	5
VIN	VF7SXHMRPJT708651	Last service date	03/12/2025		

£100 ADDITIONAL FEE
LAST SERVICE 03/12/2025 @ 34,441 MILES (6 SERVICES)

Tyres


NSF	RAPID	5.0mm
NSR	BUDGET	5.0mm
OSF	SUNNY	5.0mm
OSR	NEXEN	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Central locking
- Navigation system
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Park assist camera
- Radio/CD
- Climate control
- Solid Paint
- Traction control
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Wheel osf
Corroded
Light




2: Door osf
Dented
Over 30mm



3: Door osr
Chipped
Edge Chip




4: Wheel osr
Corroded
Light



5: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



6: Wheel nsr
Corroded
Light



7: Door nsr
Scratched
UpTo 25mm Thru Paint



8: Door nsr
Chipped
1 To 5



9: Door nsf
Chipped
Edge Chip



10: Wheel nsf
Corroded
Light



11: Bumper Front
Scratched
25 to 100mm Thru Paint



12: Bumper Front
Chipped
1 To 5



13: Bonnet
Scratched
Over 25mm Thru Paint



14: Roof
Poor Previous Repair
Paint Flake



15: Bumper Rear Moulding
Scuffed (Unpainted)
UpTo 100mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK