



# VEHICLE INSPECTION REPORT

**YP69WCW**

## Ford Focus 2.3 EcoBoost ST 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	16/01/2020	Body Style	Hatchback	Last service miles	73,919
Year	2020	Keys	2	MOT Due	15/01/2026
Mileage	84,803 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	8	Doors	5
VIN	WF0NXXGCHNKT09528	Last service date	08/01/2025		

£100 ADDITIONAL FEE Last service 08/01/2025 @ 73919 miles (8 MAIN DEALER SERVICES)

### Tyres

NSF	BUDGET	3.0mm
NSR	MICHELIN	3.0mm
OSF	BUDGET	4.0mm
OSR	MICHELIN	4.0mm
Spare		

## Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Audio remote control
- Electric sunroof
- Electrically adjustable drivers seat
- Height adjustable drivers seat
- Solid Paint
- Isofix child seat anchor points
- Central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Digital radio
- Opening panoramic glass roof
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Front parking sensor
- PAS
- Telephone
- Body coloured bumpers
- Air conditioning
- Front electric windows
- Rear electric windows
- ABS
- Side airbags
- Partial leather seat trim
- Heated front seat
- Rear parking sensor
- Trip computer
- Electric door mirrors
- Climate control
- Front head restraints
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Chipped  
Multiple Chips



No Image



3: Bumper Front  
Scratched  
Over 25mm Not Thru Paint

4: Wheel nsf  
Scratched  
Over 50mm

No Image



5: Wing nsf  
Scratched  
Over 25mm Not Thru Paint

6: Door nsf  
Chipped  
1 To 5

No Image



7: Door nsf  
Scratched  
Over 25mm Not Thru Paint

8: Door nsr  
Chipped  
1 To 5



9: Qtr Panel nsr  
Chipped  
1 To 5




10: Wheel nsr  
Scratched  
Up To 50mm



11: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



12: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint




13: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint



14: Wheel osr  
Scratched  
Over 50mm






15: Door osr  
Chipped  
1 To 5

No Image

16: Door osr  
Scratched  
Over 25mm Not Thru Paint



17: Door osf  
Chipped  
1 To 5

No Image

18: Door osf  
Scratched  
Over 25mm Not Thru Paint



19: Wing osf  
Chipped  
1 To 5



20: Wheel osf  
Scratched  
Over 50mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		