

VEHICLE INSPECTION REPORT

GV64HYY

Ford Fiesta 1.0 EcoBoost Zetec 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	28/02/2015	Body Style	Hatchback	Last service miles	96,299
Year	2015	Keys	2	MOT Due	01/08/2027
Mileage	96,939 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	5
Colour	RED	Number of stamps	9	Doors	5
VIN	WF0DXXGAKDFK40292	Last service date	06/07/2026		

Last Service - 06.07.2026 at 96299 miles (9 services)


Tyres

NSF	MATADOR	5.0mm
NSR	MATADOR	5.0mm
OSF	MATADOR	5.0mm
OSR	BUDGET	6.0mm
Spare		

Features


- Bluetooth connection
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear wiper
- Electric door mirrors
- Solid Paint
- Traction control
- Cloth seat trim
- Telephone
- Air conditioning
- ABS
- Tyre pressure monitor
- Alloy wheels
- Radio/CD
- Front electric windows
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Dented
Between 10mm + 30mm



3: Door Mirror Assy osf
Broken
Replace



4: Door osf
Chipped
1 To 5



5: Door osf
Chipped
Edge Chip




6: Door osr
Chipped
1 To 5




7: Door osr
Chipped
Edge Chip



8: Qtr Panel osr
Chipped
1 To 5



9: Bumper Rear
Scratched
Over 100mm Thru Paint



10: Qtr Panel nsr
Chipped
Over 5mm



11: Wheel nsr
Scratched
Over 50mm




12: Door nsr
Chipped
1 To 5



13: Door nsr
Chipped
Edge Chip



14: Door nsf
Chipped
1 To 5



15: Door nsf
Chipped
Edge Chip




16: Wing nsf
Chipped
1 To 5



17: Wheel nsf
Scratched
Over 50mm



18: Bumper Front
Scratched
Over 100mm Thru Paint



19: Bonnet
Chipped
Multiple Chips



20: Roof
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK