



VEHICLE INSPECTION REPORT

GY17AHD

Hyundai Ioniq 1.6 GDi Hybrid Premium 5dr DCT

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	31/03/2017	Keys	2	CAP Clean	£6,475.00
Year	2017	Service history	Yes	CAP Average	£5,650.00
Mileage	106,736 Miles Warranted	Service documents	Service Book	CAP Below	£4,850.00
Fuel Type	HYBRID ELECTRIC	Number of stamps	10	Gearbox	SEMI AUTO
Colour	WHITE	Last service date	04/11/2025	Gears	6
VIN	KMHC851CVHU028149	Last service miles	98,427	Doors	5
Body Style	Hatchback	MOT Due	30/03/2027		

Last Service - 04.11.2025 at 98427 miles (10 MAIN DEALER services)

Tyres

NSF	NEXEN	5.0mm
NSR	NEXEN	5.0mm
OSF	SUNNY	5.0mm
OSR	LAUFENN	5.0mm
Spare		


Features

- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Steel wheels
- Cruise control
- PAS
- Digital radio
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

Photos



Condition Check



Damage Photos



1: Door osf
Dented
Over 30mm



2: Door osr
Chipped
Edge Chip




3: Door osr
Chipped
Edge Chip



4: Bumper Rear
Scratched
25 to 100mm Thru Paint



5: Bumper Rear
Chipped
Multiple Chips



6: Door nsr
Dented
Between 10mm + 30mm



7: Door nsf
Dented
Between 10mm + 30mm



8: Door nsr
Chipped
1 To 5



9: Wing nsf
Chipped
1 To 5



10: Bumper Front
Chipped
Multiple Chips



11: Bumper Front
Scratched
25 to 100mm Thru Paint



12: Bonnet
Chipped
1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK