



VEHICLE INSPECTION REPORT

GU17HLO

Toyota Yaris 1.33 VVT-i Icon 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	23/03/2017	Body Style	Hatchback	Last service miles	13,028
Year	2017	Keys	2	MOT Due	22/03/2027
Mileage	22,758 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	3	Doors	5
VIN	VNKKJ3D360A423856	Last service date	18/03/2022		

£90 ADDITIONAL FEE

Last Service - 18.03.2022 at 13028 miles (3 services)

Tyres

NSF	RAPID	6.0mm
NSR	DUNLOP	5.0mm
OSF	RAPID	6.0mm
OSR	DUNLOP	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Rear wiper
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Park assist camera
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Other
N/A
N/A



2: Bumper Rear
Scratched
Over 100mm Thru Paint



3: Door nsr
Dented
2 Or Less UpTo 10mm



4: Wheel nsf
Scratched
Up To 50mm



5: Roof
Chipped
1 To 5

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK