



VEHICLE INSPECTION REPORT

EY62UEA

Vauxhall Insignia 2.0 CDTi [160] Tech Line 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	20/09/2012	Body Style	Estate	Last service miles	77,137
Year	2012	Keys	1	MOT Due	29/04/2027
Mileage	79,238 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	DIESEL	Service documents	Printout	Gears	6
Colour	BLACK	Number of stamps	6	Doors	5
VIN	W0LGM8EM9D1001546	Last service date	24/04/2026		

£90 ADDITIONAL FEE

LAST SERVICE 24/04/2026 @ 77,137 MILES (6 SERVICES) Starting to smoke

Tyres




NSF	NEXEN	3.0mm
NSR	NEXEN	6.0mm
OSF	NEXEN	3.0mm
OSR	NEXEN	6.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Radio/CD
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Service indicator
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Front armrest
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- PAS
- Digital radio
- Roof rails
- Front electric windows
- Steering wheel reach adjustment
- Drivers airbag
- Central locking

Photos





Condition Check




Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Badgedecal Front
Missing
Replace



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm




5: Wing nsf
Scratched
UpTo 25mm Thru Paint



6: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



7: A Post ns
Chipped
1 To 5



8: Door nsf
Poor Previous Repair
Rippled UpTo 30%



9: Door nsr
Poor Previous Repair
Rippled UpTo 30%



10: Wheel nsr
Scratched
Over 50mm



11: Lamp nsr
Broken
Replace




12: C Post ns
Poor Previous Repair
Poor Paint



13: Qtr Panel nsr
Rusted
Over 5mm



14: Bumper Rear
Scratched
Over 100mm Thru Paint



15: Tailgate
Scratched
Over 25mm Thru Paint



16: Qtr Panel osr
Scratched
Over 25mm Thru Paint



17: Wheel osr
Scratched
Over 50mm



18: Door osr
Scratched
Over 25mm Thru Paint



19: Door osf
Scratched
Over 25mm Thru Paint



20: Handle Outer osf
Scratched (Painted)
Over 25mm Thru Paint



21: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



22: Qtr Panel osr
Scratched
Over 25mm Thru Paint



23: Wheel osf
Scratched
Over 50mm



24: Screen Front
Chipped
UpTo 10mm



25: Roof
Chipped
Edge Chip

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK