



VEHICLE INSPECTION REPORT

BK19PBU

Skoda Karoq 1.6 TDI SE 5dr DSG

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	05/03/2019	Body Style	Estate	Last service miles	29,002
Year	2019	Keys	2	MOT Due	06/03/2027
Mileage	123,396 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	DIESEL	Service documents	Printout	Gears	7
Colour	GREY	Number of stamps	2	Doors	5
VIN	TMBKG7NU2K2014448	Last service date	12/03/2021		

£90 ADDITIONAL FEE
LAST SERVICE 12/03/2021 @ 29,002 MILES (2 SERVICES)

Tyres

NSF	PACE	5.0mm
NSR	BUDGET	6.0mm
OSF	PACE	5.0mm
OSR	BUDGET	6.0mm
Spare		

Features


- Bluetooth connection
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Cruise control
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Up To 50mm



2: Wing osf
Chipped
1 To 5



3: Door osf
Chipped
1 To 5



4: Door osf
Chipped
Edge Chip



5: Door osr
Scratched
UpTo 25mm Thru Paint



6: Door osr
Chipped
Edge Chip



7: Door osr
Dented
2 Or Less UpTo 10mm



8: Qtr Panel nsr
Chipped
1 To 5



9: Door nsr
Chipped
1 To 5



10: Door nsf
Chipped
1 To 5



11: Door nsf
Chipped
1 To 5



12: Bumper Front
Scratched
25 to 100mm Thru Paint



13: Bonnet
Chipped
1 To 5



14: Screen Front
Chipped
UpTo 10mm



15: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
		Steering	OK