



VEHICLE INSPECTION REPORT

LB02HNJ

Mercedes-Benz CLK CLK240 ELEGANCE

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	11/07/2002	Colour	SILVER	MOT Due	29/05/2026
Year	2002	VIN	WDB2093612F009650	Gearbox	AUTOMATIC
Mileage	47,042 Miles Warranted	Body Style	Coupe	Gears	5
Fuel Type	Petrol	Keys	1		

£100 ADDITIONAL FEE Radio doesn't work
Heating control buttons broken
Brake lining wear message displays on dash

Tyres


NSF	CONTINENTAL	5.0mm
NSR	BUDGET	4.0mm
OSF	GOODYEAR	Damaged
OSR	CONTINENTAL	2.0mm
Spare		

Features


- Cruise control
- Air conditioning
- Rear headrests
- Passenger airbag
- Alloy wheels
- Radio/CD
- Climate control
- Metallic Paint
- Central locking
- Body coloured bumpers
- Front electric windows
- ABS
- Remote central locking
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Wheel osf
Corroded
Light



2: Door osf
Chipped
1 To 5



3: Door osf
Chipped
Edge Chip



4: Wheel osr
Corroded
Light



5: Qtr Panel osr
Scratched
Over 25mm Thru Paint



6: Bumper Rear
Scratched
Over 100mm Thru Paint



7: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



8: Wheel nsr
Corroded
Light



9: Sill Panel Trim ns
Scratched (Painted)
Over 25mm Thru Paint



10: Door nsf
Chipped
Edge Chip




11: Wing nsf
Dented
With Paint Damage



12: Wheel nsf
Corroded
Light




13: Bumper Front
Scratched
Over 100mm Thru Paint



14: Tyre osf
Damaged
Replace



15: Bonnet
Chipped
1 To 5



16: Roof
Chipped
1 To 5




17: Other
N/A
N/A



18: Tyre osf
Damaged
Replace



19: Door Mirror Glass os
Broken
Replace



20: Tyre osf
Damaged
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	Fault
		Steering	OK