



VEHICLE INSPECTION REPORT

AK64HZR

BMW X5 sDrive25d SE 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	12/11/2014	VIN	WBAKS020900H92522	Last service date	15/03/2025
Year	2014	Body Style	Estate	MOT Due	05/04/2027
Mileage	TBC	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	DIESEL	Service documents	Printout	Gears	8
Colour	BLUE	Number of stamps	3	Doors	5


No green slip

Last Service - 15.03.25 at unknown miles (3 services)


Tyres

NSF	CONTINENTAL	4.0mm
NSR	CONTINENTAL	4.0mm
OSF	CONTINENTAL	4.0mm
OSR	CONTINENTAL	4.0mm
Spare		

Photos




Condition Check



Damage Photos



1: Seat Base Cover osf
Scuffed
Over 25mm



2: Bonnet
Scratched
Over 25mm Thru Paint



3: Bumper Front
Scratched
25 to 100mm Thru Paint




4: Bumper Front
Scratched
25 to 100mm Thru Paint



5: Wheel nsf
Scratched
Over 50mm



6: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



7: Door nsf
Dented
Over 30mm




8: Door nsf
Scratched
UpTo 25mm Thru Paint



9: Door nsr
Poor Previous Repair
Rippled UpTo 30%



10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Wheel nsr
Scratched
Over 50mm




12: Bumper Rear
Scratched
25 to 100mm Thru Paint




13: Tailgate
Chipped
1 To 5



14: Qtr Panel osr
Scratched
Over 25mm Thru Paint



15: Door osr
Scratched
Over 25mm Thru Paint



16: Door osf
Scratched
Over 25mm Thru Paint



17: Door nsr
Dented
Between 10mm + 30mm



18: Wing osf
Chipped
1 To 5



19: Wheel osf
Scratched
Up To 50mm



20: Screen Front
Chipped
UpTo 10mm



21: Roof
Scratched
Over 25mm Thru Paint

22: Tailgate
Chipped
Edge Chip

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		
Airbag light illuminated	OK	Oil warning light illuminated	OK
ABS light illuminated	OK	DPF light illuminated	OK
		Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK