



VEHICLE INSPECTION REPORT

GX17OGJ

Toyota Yaris 1.33 VVT-i Icon 5dr CVT

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 TBC

nama
GRADE
4

Details

Reg. date 01/03/2017

Year 2017

Mileage 30,470 Miles
Warranted

Fuel Type PETROL

Colour GREY

VIN VNKKJ3D3X0A415579

Body Style Hatchback

Keys 2

MOT Due 05/03/2027

Gearbox CVT

Gears 1

Doors 5

Exhaust blowing

Tyres

NSF DUNLOP 5.0mm

NSR DUNLOP 5.0mm

OSF FALKEN 6.0mm

OSR FALKEN 5.0mm


Spare

Features


- Bluetooth connection
- PAS
- Body coloured bumpers
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Remote central locking
- Cruise control
- Rear wiper
- Electric door mirrors
- Front head restraints
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Cloth seat trim
- Navigation system
- Steering wheel mounted controls
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Drivers airbag
- Traction control
- Alloy wheels
- Park assist camera
- Digital radio
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking

Photos





Condition Check



Damage Photos




1: Roof
Scratched
Over 25mm Thru Paint



2: Roof
Dented
Between 10mm + 30mm



3: Wing nsf
Chipped
1 To 5




4: Bumper Front
Scratched
UpTo 25mm Thru Paint



5: Bumper Front
Scratched
25 to 100mm Thru Paint



6: Wing nsf
Dented
With Paint Damage



7: Door nsf
Scratched
Over 25mm Thru Paint



8: Door nsr
Chipped
1 To 5




9: Bumper Front
Scratched
Over 100mm Thru Paint



10: Qtr Panel osr
Dented
Between 10mm + 30mm



11: Qtr Panel osr
Chipped
1 To 5



12: Door osr
Scratched
Over 25mm Thru Paint



13: Door osf
Scratched
Over 25mm Thru Paint



14: Wing osf
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK