

VEHICLE INSPECTION REPORT

GU69AAO

Skoda Karoq 1.5 TSI SE 5dr DSG

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 TBC

nama
GRADE
2

Details

Reg. date	21/11/2019	Colour	WHITE	MOT Due	20/11/2026
Year	2019	VIN	TMBKR7NU7LJ008498	Gearbox	SEMI AUTO
Mileage	47,449 Miles Warranted	Body Style	Estate	Gears	7
Fuel Type	PETROL	Keys	2	Doors	5

Tyres



NSF	FALKEN	5.0mm
NSR	FALKEN	5.0mm
OSF	FALKEN	5.0mm
OSR	FALKEN	5.0mm


Spare

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Space saver spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Cruise control
- Service indicator
- Electric door mirrors
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Cloth seat trim
- PAS
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Traction control
- Alloy wheels
- Rear parking sensor
- Digital radio
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
1 To 5



3: Wheel nsf
Scratched
Up To 50mm



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Door nsf
Chipped
Edge Chip



6: Wheel nsr
Scratched
Up To 50mm



7: Bumper Rear
Scratched
25 to 100mm Thru Paint



8: Wheel osr
Scratched
Up To 50mm



9: Wing of
Chipped
1 To 5

10: Roof
Chipped
Edge Chip

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK