



VEHICLE INSPECTION REPORT

GJ22FZO

Hyundai I10 1.0 MPi SE Connect 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	VAT Qualifying
		V5	Present



Details

Reg. date	15/03/2022	Body Style	Hatchback	Last service miles	23,476
Year	2022	Keys	2	MOT Due	14/03/2027
Mileage	26,026 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	PETROL	Service documents	Service Book	Gears	5
Colour	GREEN	Number of stamps	4	Doors	5
VIN	NLHDN51AYNZ119609	Last service date	25/02/2026		

LAST SERVICE 25/02/2026 @ 23,476 MILES (4 SERVICES)

Tyres


NSF	ROYALBLACK	5.0mm
NSR	KUMHO	5.0mm
OSF	FALKEN	5.0mm
OSR	KUMHO	5.0mm
Spare		

Features


- Bluetooth connection
- Telephone
- Air conditioning
- Metallic Paint
- Traction control
- Cloth seat trim
- Park assist camera
- Radio/CD
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Rear parking sensor
- Body coloured bumpers
- Rear electric windows
- Drivers airbag
- Central locking
- Rear wiper
- Electric door mirrors
- Rear headrests
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos




1: Door osr
Scratched
UpTo 25mm Thru Paint



2: Bumper Front
Chipped
1 To 5



3: Bonnet
Chipped
1 To 5



4: Screen Front
Chipped
UpTo 10mm



5: Door osf
Dented
Between 10mm + 30mm



6: Door osr
Dented
Between 10mm + 30mm



7: Door nsf
Dented
Between 10mm + 30mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK